

Report Of Passed And Failed Appliances
For all Sites and Locations

Appliance Description	Appliance Id	Test Date	Vis	Pol	Earth Cont Ohms	Insulation MOhms	Load kVA	Leakage mA	Touch Leak mA	Sub Leak mA	Flash mA
SHS - IT SUPPORT											
TOSH PSU	NEW	28/06/10	P	S	>19.99 F	>200 P	S	S	S	<0.10 P	S
Total Appliances:											1
SHS - ROOM 07											
PC	70090	28/06/10	P	S	0.03 P	>200 P	S	S	S	0.14 P	S
Total Appliances:											1
Total Appliances For Report:											2